

Date Completed: _____ Failure Code: _____

Completed By : _____ Signature : _____

Accepted By : _____ Signature : _____

**** Delay Codes Legend ****

W=Whse C=CrSp T=Tag TL=Tool P=Plan
 ** Record Time Daily ** Delays

Step	Job Scope	MN	DY	Safety and Additional Information
------	-----------	----	----	-----------------------------------

1 RETURN PRINTED OUTPUT BOARD TO FOXBORO
FOR REPAIR/REPLACEMENT.

INSURE THERE IS A SHORT DESCRIPTION OF
THE PROBLEM FOUND.

ADDITIONAL INSTRUCTIONS BY SUPERVISOR.

STK NO: 2627
QTY: 1
ORIG WO: 02-60456-5
STK ISSUE: 245016

ITEM DESCRIPTION:
BOARD, FOXBORO (CCS) ANALOG CONVERTER,
DUAL DC
MILLI-AMP TO DIGITAL OUTPUT, 4 TO 20 MADC
EACH
CHANNEL, ISOLATED OUTPUT.
FOXBORO P/N 3A2-D21B

[illegible]

**** IMPORTANT NOTICE ****

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



CREW: 89

WORK ORDER TYPE: REBUILDS

02-60456-24

ISSUE DATE 01/06/11

Page 2 Of 2

** Work Order Parts List **

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	DIRECT	03-32275	05/01/03	EA	1	0	1

IP7_037384